Bugfixes
# 2016-17.42

Technical Inquiries

Please ask the responsible contact person in our support department.
E-mail: e3-support@zuken.com

Contact

Zuken E3 GmbH
Laemmerweg 55
D-89079 Ulm/Einsingen

Phone : +49 7305 9309-0
Fax:+49 7305 9309-99
Web: http://www.zuken.com
E-mail: e3-info@zuken.com

Bugfixes

INFORMATION	
	When opening a project with the new version (2016-17.42), projects of the directly previous version (2016-17.41)

are converted and can no longer be opened with the previous version
　　　　[ ] Single-User
　　　　[ ] Multi-User

are not converted and can still be opened with the previous version
　　　　[x] Single-User
　　　　[x] Multi-User

COM Registration
[x] the COM library has been changed and should be registered again
　　　　(start the program as ADMIN using „E3.series.exe /register") |

The bug fixes are sorted and listed by designer number(s). This enables you, for example, to easily search for bugs reported to our support office.

Designer-16284	The expression 'Wires' in terminal plan (if wires are output) should be displayed in the defined project language (text database)
Designer-24827	COM method 'Pin.HasDevice' on wire returns true or false depending on what is connected to the wire's end
Designer-30401	When comparing two E3.series projects, the text is not displayed with the font size given in the parameter 'FontSize' (ini-file) after text changes
Designer-30779	COM: Method "prj.DeleteMultiuser" doesn't delete the project when an opened project has been closed with "prj.Close" before
Designer-30910	At split/merge of connector pins in formboard the following message appears 'No formboard symbols defined for this connector. Please choose a symbol.'
Designer-31100	Text type "Time of Modification" (#2009) is not updated on terminal plan sheet when adding new terminal
Designer-31437	The command 'Swap Symbol' doesn't work for a connector on a hierarchical block when it is also placed within the hierarchy 'Symbol 'xxx' can't be placed on following position (xxx.xxx) of sheet 'xxx'.'
Designer-31456	Hyperlink doesn't support "https"
Designer-31469	Not all component versions are displayed in the component table when using the 'Search' function - 'Blank'- or 'sys' versions are missing
Designer-31497	The COM method "Dev.SetOptionExpressionsWithFlags" doesn´t

	work correctly when called internally
Designer-31526	After cutting pins of a model with Step models on a model sheet within the database editor, the sheet appears in 3D mode
Designer-31532	The COM method "Option.GetPinIds" doesn't consider cable conductors
Designer-31569	Long-running problem when copying a block with a block connector component with 300 pins
Designer-31576	Attribute text template symbol on a mating connector, that has its Device Designation assigned by a block, isn't updated automatically
Designer-31593	The COM method "Graph.SetArrows" works only with lines
Designer-31596	Inactive commands in context menu of connector device
Designer-31598	Trigger 'AfterOpenProject' is executed before 'AfterLaunchE3'
Designer-31599	Foreign language texts in the info column at selection of connector pin terminals are not translated in all dialogs
Designer-31609	The COM method "GetSignalname" from the Connectioninterface doesn't work for connections with wires
Designer-31633	COM: Delete of SignalClassInterface returns 0 (successful) in case of error
Designer-31636	After having saved a project with "Save current configuration without variants / options", conductor namings disappear when deleting and placing a symbol again
Designer-31639	GraphicalCompare: Graphical comparison of two E3S files results in structure nodes hanging on faulty/unexpected locations/structure nodes
Designer-31642	Paste of copied objects might take very long
Designer-31664	The export of a sub-circuit may take very long
Designer-31672	Model characteristic can't be changed by device properties
Designer-31730	The COM command "GetSignalname" from the Connectioninterface doesn't work for connections which are also placed on a Formboard
Designer-31733	After using 'Merge all non-colliding' shields are incorrectly assigned
Designer-31734	Wires are saved to the project after 'Merge all non-colliding' although the setting 'Create unique names' (for wires) is checked
Designer-31744	Performance problems might appear when moving objects on a sheet
Designer-31749	The COM function 'Job.JumpToID()' doesn't highlight wires in E3.panel

Americas

North America
Zuken USA Inc.
Westford, MA 01886, USA
Tel: +1 978 692 4900

Asia

Japan
Zuken (World Wide Head Office)
Yokohama, Kanagawa 224-8585, Japan
Tel: +81 45 942 1511

China
CIM-TEAM Software Technology Co., Ltd.
Changning District, Shanghai, China, 200336
Tel: +86-21-52280180

Korea
Zuken Korea Inc.
Seoul 135-283, Korea
Tel: +82 2 5648031

Singapore
Zuken Singapore Pte Ltd.
#22-05 Gateway East, Singapore 189721
Tel: +65 6392 5855

Taiwan
Zuken Taiwan Inc.
Taipei 110, Taiwan
Tel: +886 2 7718 1116

Europe

Germany
Zuken GmbH (European HQ)
D-85399 Hallbergmoos, Germany
Tel: +49 89 7104059 00

Zuken E3 GmbH
D-89079 Ulm, Germany
Tel: +49 7305 9309 0

Zuken E3 GmbH
D-30659 Hannover, Germany
Tel: +49 511 8595 9489

Switzerland
Zuken E3 GmbH
CH-5506 Mägenwil, Switzerland
Tel: +41 56 437 08 90

United Kingdom
Zuken UK Ltd.
Bristol, BS32 4RF, UK
Tel: +44 1454 207 801

France
Zuken S.A.
#91974 Les Ulis Cédex, France
Tel: +33 1 69 29 48 00

Italy
Zuken S.r.l.
20090 Milanofiori Assago, Milan, Italy
Tel: +39 02 575 921

Netherlands
Zuken GmbH
NL-6075 HA Herkenbosch, The Netherlands
Tel: +31 475 520 998

www.zuken.com/e3

ZUKEN®